#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

### WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-010899

Address: 333 Burma Road **Date Inspected:** 16-Sep-2009

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name: CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component:** Deck Panel

#### **Summary of Items Observed:**

Bridge No. 34-0006 Component: Deck Panels

Summary of Items Observed: On this day Caltrans OSM Quality Assurance (QA) Inspector Gary Richmond was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhen Hua Port Machinery Company (ZPMC) at Chang Xing Island in Shanghai, China. QA Inspector observed the following:

The QA Inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested by ZPMC MT personnel. This QA Inspector generated a TL-6028 MT report on this date. The weld designation numbers is as follows:

DP 158-001 Green Tag #10476 DP 295-001 Green Tag #10477

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

## **Summary of Conversations:**

No relevant conversations noted.

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, who represents the Office of Structural Materials for your project.

Inspected By:	Richmond, Gary	Quality Assurance Inspector
Reviewed By:	Carreon, Albert	QA Reviewer